

Vehicle diagnostic report



Shop Name: www.диагностика.бг
 Address: Пловдив
 Phone: 0877768013
 Email: Kalin_kulchew@abv.bg

VIN: 谱UZZZ4B73N084044

Year: 2003

Make: Audi

Model:

Odometer:

Vehicle Software Version: V28.55

Diagnostic Application Version: 3.12.036

Test Time: 2019-10-18 18:20:41

Diagnostic path: Health Report

Inspection Result



Diagnostic Result

Fault	(9)	
01 Engine Control Module 1	(5)	Abnormal
	01375 Engine Mounting Valve - Stage 1	Output does not switch/short circuit to B+
	01318 Injection Pump Control Module	No communication
	00628 Positioning Level Monitoring	Short circuit to B+
	P1570 Engine Control Module (ECM) Disabled	
	00550 Start Of Injection Regulation	Control limit exceeded
02 Transmission Control Module	(4)	Abnormal
	P0702 Transm. Contr. System : electrical	
	P0702 Transm. Contr. System : electrical	
	P1753 Tiptronic Switch : implausible Signal	
	P1814 Press. Ctrl. Valve 1 : Open Circuit/short Circuit To Ground	
03 Brakes 1	(1)	Abnormal
	P1857 Load Signal : error Message From Engine Contr.	
08 Air Conditioning	(4)	Abnormal

	00779 Outside Temperature Sensor	Open circuit/short circuit to B+
	01592 Air Quality Sensor	Faulty
	01317 Instrument Cluster Control Module	No communication
	01314 Engine Control Module (ECM)	No communication
15 Airbag	(1)	Abnormal
	00532 Supply Voltage	Lower Limit Exceeded
17 Dash Board	(3)	Abnormal
	01300 Ctrl. Module For Navigat. Sys. With CD Drive	No communication
	01304 Radio	No communication
	01314 Engine Control Module (ECM)	No communication
35 Central Locking Control Module	(9)	Abnormal
	01374 Alarm Triggered By Terminal 15	
	01369 Alarm Triggered By Bonnet Switch	
	01368 Alarm Triggered By Luggage Compartment Switch	
	01560 Front Passenger Door	does not unlock
	01562 Right Rear Door	does not unlock
	01560 Front Passenger Door	deadlock does not engage
	01562 Right Rear Door	deadlock does not engage
	01573 Alarm Triggered By Door Contact Switch - Rear Left	
	01134 Alarm Horn	No communication
55 Headlight Regulation	(3)	Abnormal
	01535 Activation For Right Headlamp Beam Adjustment Motor	Open circuit/short circuit to B+
	01534 Activation For Left Headlamp Beam Adjustment Motor	Open circuit/short circuit to B+
	00532 Supply Voltage	Signal too low
56 Radio	(1)	Abnormal
	00668 Vehicle Voltage Terminal 30	Signal too low
Normal	(1)	
25 Immobilizer		Normal