


Vehicle diagnostic report



Shop Name: obd2 Kulchev
 Address:
 Telephone: 0877768013
 Email : Kalin_kulchew@abv.bg
 Fax:

Make: Mercedes
 Model: 204.008 - C 220 CDI Sedan
 Year:
 VIN: WDD2040081A239933
 ODO: 181321km
 Vehicle Software Version: V49.10
 Diagnostic Application Version: 3.11.030
 Test Time: 2019-03-16 12:55:59
 Diagnostic path: Automatically Search



Diagnostic Result

Fault	(3)	
ECM - Engine Control Module(CDI)	(3)	Abnormal
	2299 Check Component "Diesel Particulate Filter".The Fill Level Of The Diesel Particulate Filter Is Too High.	CURRENT And STORED
	22e0 N30/4 (Electronic Stability Program Control Unit)	STORED
	2373 Check Injector Injection Quantity Adjustment.	STORED
Driver-side SAM - Front Signal Acquisition And Actuation Module	(2)	Abnormal
	U141E00 An Implausible Signal From Switch " Exterior Illumination" Was Received._	STORED
	B237971 The Wiper Motor Has A Malfunction.The Actuator Is Blocked.	STORED
REAR SAM - Rear Signal Acquisition And Actuation Module	(1)	Abnormal
	B16EB15 The Output For The Right License Plate Lamp Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	CURRENT And STORED
Normal	(13)	
EZS - Electronic Ignition lock(N73)		Normal
SCM - Steering Column Module		Normal
SRS - Supplemental Restraint System		Normal

CGW[ZGW] - Central Gateway	Normal
COU[ZBE] - Audio/COMAND Operating Unit	Normal
ZAN - Audio/COMAND Display	Normal
Audio/COMAND - Audio Or COMAND(A2-A2/56-A40/3)	Normal
IC - Instrument cluster(A1)	Normal
DCU_LR - Left Rear door(N69/3)	Normal
DCU_RR - Right Rear door(N69/4)	Normal
DCU_LF - Left Front door(N69/1)	Normal
DCU_RF - Right Front door(N69/2)	Normal
AC - Air Conditioning(N22/7)	Normal