

Vehicle diagnostic report



Shop Name: WWW.ДИАГНОСТИКА.БГ
 Address: диагностика Пловдив
 Phone: 0877768013
 Email: Kalin_kulchew@abv.bg

VIN: WDDLJ7DBXCA044509

Year:

Make: Mercedes

Model: 218.373 - CLS 500 BI

Odometer: 106323km

Vehicle Software Version: V49.21

Diagnostic Application Version: 3.12.035

Test Time: 2019-07-14 11:39:16

Diagnostic path: Automatically Search

Inspection Result



Diagnostic Result

Fault	(10)
ME - Motor Electronics	(1)
IRS-HRA - Outer Right Rear Intelligent Radar Sensor system(B29/5)	(1)
IRS-HLA - Outer Left Rear Intelligent Radar Sensor system(B29/4)	(1)
PTS - PARKTRONIC(N62)	(6)

P226321 The Boost Pressure Deviates From The Specified Value.The Signal Amplitude Is Less Than The Minimum Amplitude.

Abnormal
STORED

Abnormal

550400 Component "B29/5 (Right Rear Bumper Intelligent Radar Sensor)" Is Disrupted By Interference From An External Transmitter.

STORED

Abnormal

580400 Component "B29/4 (Left Rear Bumper Intelligent Radar Sensor)" Is Disrupted By Interference From An External Transmitter.

STORED

Abnormal

B125323 The Inner Right Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.

CURRENT And
STORED

B125823 The Center Right Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.

CURRENT And
STORED

B124E23 The Inner Left Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.

CURRENT And
STORED

B124923 The Center Left Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.

CURRENT And
STORED

B124423 The Outer Left Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.

CURRENT And
STORED

TPMS - Tire Pressure Monitoring System(N88)	B125D23 The Outer Right Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low. (1)	CURRENT And STORED Abnormal
	551c00 The Tire Pressure Sensors Were Not Detected.	CURRENT And STORED
RevETR_LF - Left Front Reversible Emergency Tensioning retractor(A76)	(4)	Abnormal
	520501 The CAN Message From Control Unit "Central Gateway" Is Faulty.	STORED
	520201 The CAN Message From Control Unit "A1 (Instrument Cluster)" Is Faulty.	STORED
	520400 No CAN Message Was Received From Control Unit "Central Gateway".	STORED
	640300 Software Error	STORED
Driver-side SAM - Front Signal Acquisition And Actuation module(N10/1)	(2)	Abnormal
	B16BF15 The Left Side-marker Lamp Has A Malfunction. There Is A Short Circuit To Positive Or An Open Circuit.	Current and stored
	B16C315 The Right Side-marker Lamp Has A Malfunction. There Is A Short Circuit To Positive Or An Open Circuit.	Current and stored
MIF - Media Interface	(1)	Abnormal
	1614 An Internal Control Unit Reset Is Being Performed.	STORED
ESA 'Driver' - Electric Seat Adjustment 'Drive'(N32/1)	(1)	Abnormal
	9eaf97 Easy Entry/Exit Has A Malfunction.The System Function Is Restricted.	CURRENT And STORED
AC - Air Conditioning(N22/7)	(15)	Abnormal
	960315 The Right Sun Sensor Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	STORED
	905807 The Actuator Motor For The Fresh Air/Recirculated Air Flap Has A Malfunction.There Is A Mechanical Fault.	CURRENT And STORED
	910387 The Actuator Motor For Air Flap " Right Center Vent" Has A Malfunction.The Message Is Missing.	CURRENT And STORED
	90ff87 The Actuator Motor For Air Flap " Left Center Vent" Has A Malfunction.The Message Is Missing.	CURRENT And STORED
	90ef87 The Actuator Motor For Air Flap " Left Footwell Vent" Has A Malfunction.The Message Is Missing.	CURRENT And STORED
	90b387 Electric Heater Booster 1 Has A Malfunction.The Message Is Missing.	CURRENT And STORED
	905287 The Actuator Motor For The Rear Blend Air Flap Has A Malfunction.The Message Is Missing.	CURRENT And STORED
	917487 The Actuator Motor For Air Flap " Diffuser Outlet" Has A Malfunction.The Message Is Missing.	CURRENT And STORED
	918987 The Actuator Motor For The Ram Air Flap Has A Malfunction.The Message Is Missing.	CURRENT And STORED
	912787 The Air Quality Sensor Has A Malfunction.The Message Is Missing.	CURRENT And STORED
	90f387 The Actuator Motor For Air Flap " Right Footwell Vent" Has A Malfunction.The Message Is Missing.	CURRENT And STORED

d00900 LIN Bus 2 Has A Malfunction._	CURRENT And STORED
913652 The Measurement Run For Actuator Motors For Air Flaps Has A Malfunction.The Component Has Not Been Put Into Operation.	CURRENT And STORED
913500 The Number Of Actuator Motors For Air Flaps Is Faulty._	CURRENT And STORED
a22d00 The Automatic Address Allocation Or The Programming Is Faulty._	CURRENT And STORED

Normal (29)

FSCU - Control Unit'Fuel pump'(N118)	Normal
ISM - Shift module(A80)	Normal
TCM - Transmission Control Module	Normal
AIRMATIC - AIRMATIC(N51/3)	Normal
EPS - Electronic Power Steering(N68)	Normal
ESP - Electronic Stability program(N30/4)	Normal
MFK - Multifunction camera(A40/11)	Normal
OCP - Overhead Control panel(N70)	Normal
EZS - Electronic Ignition lock(N73)	Normal
KG - KEYLESS GO(N69/5)	Normal
SCCM - Steering Column module(N80)	Normal
HKS - Tailgate Control	Normal
RevETR_RF - Right Front Reversible Emergency Tensioning retractor(A76/1)	Normal
Rear SAM - Rear Signal Acquisition And Actuation module(N10/2)	Normal
SRS - Supplemental Restraint system(N2/10)	Normal
XALWA_L - Left Xenon headlamp(E1n1)	Normal
XALWA_R - Right Xenon headlamp(E2n1)	Normal
CGW[ZGW] - Central gateway(CGW[ZGW])	Normal
ZBE - Audio/COMAND Operating unit(A40/9)	Normal
ZAN - Audio/COMAND display(A40/8)	Normal
SOUND - Bass Amplifier	Normal
IC - Instrument cluster(A1)	Normal
ESA'Front Passenger' - Electric Seat Adjustment 'Front passenger'(N32/2)	Normal

AMKS_LF - Active Multicontour seat(N32/19)	Normal
PPAMKS - Pneumatic Pump For Active Multicontour seat(M40/1)	Normal
DCU_LR - Left Rear door(N69/3)	Normal
DCU_RR - Right Rear door(N69/4)	Normal
DCU_LF - Left Front door(N69/1)	Normal
DCU_RF - Right Front door(N69/2)	Normal