

Vehicle diagnostic report



Shop Name: www.диагностика.бг
 Address: Пловдив
 Phone: 0877768013
 Email: Kalin_kulchew@abv.bg

VIN: VF3LB9HCGDS237817

Year: 2013

Make: Peugeot

Model: 308(T9)

Odometer: 75723 km

Vehicle Software Version: V43.55

Diagnostic Application Version: 3.12.035

Test Time: 2019-06-28 17:30:59

Diagnostic path: Automatically Search>308(T9)>Health Report

Inspection Result



Diagnostic Result

Fault (14)

Fault	(14)	
Built-in Systems Interface(Bsi)	(12)	Abnormal
	U1F00 Fault Event Not Stored In The Faults Log	Permanent
	B180E Fault In Authenticating The Hands-free Remote Control Not Present In The Reader	Intermittent
	B173D Fault In Identifying The Mechanical/electronic Key Or The Hands-free Remote Control Present In The Reader	Intermittent
	B1718 Remote Control Not Synchronised	Intermittent
	B1713 Rear Right Door Locking Status Fault	Intermittent
	B1714 Rear Left Door Locking Status Fault	Intermittent
	B1715 Lack Of Coherence Between The Vehicle Locking Status And The Locking Status Of The Front Right Door Lock	Intermittent
	B1716 Lack Of Coherence Between The Vehicle Locking Status And The Locking Status Of The Front Left Door Lock	Intermittent
	B1811 Fault On The Diesel Fuel Additive Pump	Intermittent
	B120A Collision Risk Alert Function Fault	Permanent
	B1209 Distance Alert Function Or Adapted Cruise Control Function Information Fault	Intermittent
	B120D Automatic Braking On Risk Of Collision Function Fault	Permanent
Engine ECU	(1)	Abnormal
	P0494 Fan. Twin Speed: Incoherence Between The Setting (Slow Speed) And The Status Of The Cooling Fan	Intermittent
Engine Relay Unit	(3)	Abnormal
	U1F04 Engine Fuse Box ECU Internal Fault	Temporary

	B1192 Right-hand Headlamp Fan Fault	Temporary
	B1193 Left-hand Headlamp Fan Fault	Temporary
Switch Module Under The Steering Wheel	(2)	Abnormal
	U1F2A Absence Of Communication With The Integral Controls Steering Wheel ECU	Temporary
	U1F00 Event Not Recorded Fault	Permanent
Power Steering GEP	(1)	Abnormal
	B1406 Overheating Of The Power Steering Motor Or ECU. Not Characterised	Intermittent
Multiplexed Additive Pump ECU	(1)	Abnormal
	B100C ECU Supply Fault	Temporary
Vehicle Distance Assistance	(2)	Abnormal
	B1210 Disalignment Fault In The Distance Alert Sensor	Permanent
	U1F00 Event Not Recorded Fault	Permanent
Steering Wheel With Integral Controls(Vci)	(1)	Abnormal
	U1F1A Fault With Transmission By The Top-of-column On The LIN	Temporary
Multifunction Display	(3)	Abnormal
	B1004 Touch Screen Internal Fault	Temporary
	U1F3E Absence Of Communication With The Telematic Unit	Temporary
	U1F18 Touch Screen Not Communicating On The Multimedia CAN	Temporary
Rain/ Brightness Sensor	(3)	Abnormal
	U1F03 Absence Of Communication Fault With The Built-in Systems Interface	Temporary
	U1807 Park Information Fault	Temporary
	B100B Operating Temperature Fault	Temporary
Parking Aid	(3)	Abnormal
	U1F00 Event Not Recorded Fault	Permanent
	B1225 Inner Front Right Parking Assistance Sensor Fault	Temporary
	B1226 Outer Front Right Parking Assistance Sensor Fault	Temporary
Hands Free Control Kit	(3)	Abnormal
	U1F00 Event Not Recorded Fault	Permanent
	U1F03 Absence Of Communication Fault With The Built-in Systems Interface	Temporary
	B1724 Accesses Unlocking Sensor Fault (Front Right-hand Door)	Temporary
Multiplexed Control Panel	(1)	Abnormal
	B1004 ECU Internal	Temporary
Instrument Panel	(1)	Abnormal
	B1003 Secure Configuration Fault	Permanent
Normal	(13)	

Anti-lock Braking System (ABS) Or Electric Stability Program (ESP)

Normal

Air Bags

Normal

Headlamp Height Corrector

Normal

Supply Protection And Management Unit	Normal
Driver's Door Control Panel	Normal
Electronic Key Reader	Normal
Electric Steering Lock	Normal
Telematics Unit(Rtx) Or Radio Navigation	Normal
Air Conditioning	Normal
Battery Charge Status Unit	Normal
Matrix Screen Integral To The Instrument Panel	Normal
Seat Belt Not Fastened LED Unit(Tnb)	Normal
Voltage Retaining Device	Normal