

Vehicle diagnostic report



Shop Name: WWW.ДИАГНОСТИКА.БГ
 Address: диагностика Пловдив
 Phone: 0877768013
 Email: Kalin_kulchew@abv.bg

VIN: TMBHC46YX23309913

Year: 2002

Make: Skoda

Model:

Odometer:

Vehicle Software Version: V28.15

Diagnostic Application Version: 3.12.035

Test Time: 2019-07-17 07:34:36

Diagnostic path: Health Report

Inspection Result



Diagnostic Result

Fault		(4)	
01 Engine Control Module 1	(7)		Abnormal
		P1443 Potentiometer For Exhaust Gas Recirc. : signal Too Low P1553 Altitude Sensor Signal/intake Manifold Pressure : implausible Ratio P1440 EGR Vacuum Regulator Solenoid Valve : open Circuit P1349 Ignition Output 2 : Open Circuit P1158 Manifold Abs. Press. Sens. : implausible Signal P1172 Throttle Drive Angle Sensor 2 : Signal Too Low P1544 EPC Throttle Drive Angle Sensor : signal Too High	
03 Brakes 1	(1)		Abnormal
		01314 Engine Control Module (ECM)	Please read DTC
09 Central Electrics	(1)		Abnormal
		01336 Combination Comfort Databus	In single wire mode
19 Gateway	(1)		Abnormal
		01336 Combination Comfort Databus	In single wire mode
Normal		(6)	
08 Air Conditioning			Normal
15 Airbag			Normal
17 Dash Board			Normal
25 Immobilizer			Normal

44 Steering Assistance
46 Central Module
Comfort System

Normal
Normal