

Vehicle diagnostic report



Shop Name: www.диагностика.бг

Address: Пловдив

Phone: 0877768013

Email: Kalin_kulchew@abv.bg

VIN: --

Year: 2001MY

Make: Toyota

Model: COROLLA

Odometer:

Vehicle Software Version: V49.30

Diagnostic Application Version: 3.12.035

Test Time: 2019-06-07 11:28:11

Diagnostic path: 16PIN DLC(Europe and Other) > Automatically Search > 2006.03- > Others

Inspection Result



Diagnostic Result

Fault (1)

SRS Airbag	(8)	Abnormal
B1100 Airbag Sensor Assembly		Current
B0100 Short in Driver's Squib Circuit		History
B0111 Open in Side Squib(RH)Circuit		History
B0116 Open in Side Squib(LH)Circuit		History
B0131 Open in Pretensioner Squib(RH)Circuit		History
B1100 Airbag Sensor Assembly		History
B1135 Half Connection in Airbag Sensor Assembly Connector		History
B1140 Side Airbag Sensor Assembly(RH)		History

Normal (3)

Engine and ECT	Normal
ABS/VSC/TRC	Normal
Immobiliser	Normal