

Vehicle diagnostic report



Shop Name: WWW.ДИАГНОСТИКА.БГ

Address: диагностика Пловдив

Phone: 0877768013

Email: Kalin_kulchew@abv.bg

VIN:
 Year:
 Make: BMW
 Model: 3 Series
 Odometer:
 Vehicle Software Version: V50.26
 Diagnostic Application Version: V3.12.035
 Test Time: 2019-08-01 08:10:28
 Diagnostic path: Manually Select > 3 Series > 3'_E46 > Health Report > Fault Report

Inspection Result



Diagnostic Result

Fault (1)

ECM (Engine Control
Module - DME/DDE)

(7)

Abnormal

12 DME: Signal, exhaust-camshaft sensor (OBDII: P1397; EUIII: P0340)
 E4 DME: Fuel trim bank 2, permissible range exceeded (OBDII: P1189; EUIII: P0173)
 D8 DME: Signal, ox.sensor after cat.conv., bank 2, no signal (OBDII: P0156; EUIII: P0156)
 DD DME: Voltage, ox. sensor 2 after cat., sensor too slow (OBDII: P1185; EUIII: P0160)
 9A DME: Signal, ox.sensor before cat.conv., bank 2, min. value undershot (OBDII: P0150; EUIII: P0150)
 E3 DME: Fuel trim bank 1, permissible range exceeded (OBDII: P1188; EUIII: P0170)
 CB DME: Fuel trim bank 2 control limit (OBDII: P0173; EUIII: P0173)

Normal (0)