

## Vehicle diagnostic report



Shop Name: WWW.ДИАГНОСТИКА.БГ

Address: диагностика Пловдив

Phone: 0877768013

Email: Kalin\_kulchew@abv.bg

VIN: SALLSAA748A150635

Year: 2008

Make: Landrover

Model: Range Rover Sport

Odometer:

Vehicle Software Version: V33.61

Diagnostic Application Version: 3.12.036

Test Time: 2019-08-19 14:27:56

Diagnostic path: Automatically Search &gt; Health Report

## Inspection Result

## Diagnostic Result

Fault	( 7 )	
RLM (Ride level control module)	( 4 )	Abnormal
	C1A04-1c Front right height sensor	Historic
	U0416-86 Invalid data received from vehicle dynamics control module	Historic
	U0155-87 Lost communication with instrument cluster control module	Historic
	U0434-86 Invalid data received from dynamic response module.	Historic
AAM (Audio amplifier module)	( 1 )	Abnormal
	B1A04-13 Speaker 4 circuit	Permanent
ACM (Audio front control module)	( 1 )	Abnormal
	U3000-04 Control module	Historic
AHCM (Auxiliary heater control module)	( 7 )	Abnormal
	B1D29-93 No start, even after restart attempt	Intermittent
	B1D31-94 Flame detected prior to normal operation	Intermittent
	B1D34-68 Heater in lock out mode	Permanent
	U1A37-87 Crash status telegram	Permanent
	U0164-87 Lost communication with heating ventilation and air conditioning control module	Permanent
	U1A44-6c Fuel level	Permanent
	U3000-55 Control module	Intermittent
BCM (Body control module)	( 18 )	Abnormal
	B1A00-16 Control module	Intermittent
	B1B01-87 Key transponder	Intermittent
	B1B85-49 Memory control module	Intermittent
	B1B86-93 Seat height motor relay	Intermittent
	B1B87-3a Seat height motor hall sensor	Intermittent
	B1B88-93 Seat slide motor relay	Intermittent

	B1C15-3a Passenger's up/down mirror motor feedback circuit	Intermittent
	B1C16-3a Passenger's left/right mirror motor feedback circuit	Intermittent
	B1C31-93 Steering column motor relay	Intermittent
	B1C99-15 Right corner lamp circuit	Intermittent
	B1D01-15 Right low beam circuit	Intermittent
	B1D06-11 Left turn signal circuit	Intermittent
	B1D06-15 Left turn signal circuit	Intermittent
	B1D07-15 Right turn signal circuit	Intermittent
	B1D08-11 Left trailer turn signal circuit	Intermittent
	U0155-87 Lost communication with instrument cluster control module	Intermittent
	U0164-87 Lost communication with heating ventilation and air conditioning control module	Intermittent
	U2001-68 Reduced system function	Intermittent
FEM (Front entertainment control module)	( 2 )	Abnormal
	B1A89-11 Satellite antenna	Intermittent
	U3000-68 Control module	Intermittent
HVAC (Heating ventilation and air conditioning control module)	( 7 )	Abnormal
	B1B74-00 Front foot-defrost mode stepper actuator	Intermittent
	B1B75-00 Front foot-face mode stepper actuator	Intermittent
	B1B76-00 Front left air blend stepper actuator	Intermittent
	B1B77-00 Front right air blend stepper actuator	Intermittent
	B1B78-84 System pressure	Historic
	B1B78-85 System pressure	Historic
	U0300-55 Internal control module software incompatibility	Intermittent
Normal	( 2 )	
TEL (Cellular telephone control module)		Normal
TMC (Traffic message channel module)		Normal