

Vehicle diagnostic report



Shop Name: www.диагностика.бг

Address: Пловдив

Phone: 0877768013

Email: Kalin_kulchew@abv.bg

VIN: YG85532*****

Year:

Make: Ford

Model: Focus

Odometer:

Vehicle Software Version: V47.55

Diagnostic Application Version: 3.12.035

Test Time: 2019-06-04 16:32:42

Diagnostic path: Automatically Search > Health Reports

Inspection Result



Diagnostic Result

Fault (2)

PATS (Passive Anti-Theft System) (5)

Abnormal

P1120 Throttle Position Sensor Circuit Too Low - RATCH Too Low

Continuous Memory DTCs
-

P0122 TP (Throttle Position) Sensor Circuit Low Input

Continuous Memory DTCs
-

P1000 On-Board Diagnostic (OBD) Systems Readiness Test Incomplete

Continuous Memory DTCs
-

P1125 TP (Throttle Position) Sensor Circuit Intermittent Fault

Continuous Memory DTCs
-

P0171 System Too Lean, Bank 1

Continuous Memory DTCs
-

PCM (Powertrain Control Module) (5)

Abnormal

P1120 Throttle Position Sensor Circuit Too Low - RATCH Too Low

Continuous Memory DTCs
-

P0122 TP (Throttle Position) Sensor Circuit Low Input

Continuous Memory DTCs
-

P1000 On-Board Diagnostic (OBD) Systems Readiness Test Incomplete

Continuous Memory DTCs
-

P1125 Throttle Position Sensor Noisy Signal

Continuous Memory DTCs
-

P0171 System Too Lean, Bank 1

Continuous Memory DTCs
-

Normal

(4)

ABS/TCS (Anti-Lock Braking System/Traction Control Module)

Normal

CTM (Central Timer Module)

Normal

HEC (Hybrid Electronic Cluster)

Normal

ECS (Electronic Crash Sensor)

Normal