

## Vehicle diagnostic report



Shop Name: www.диагностика.бг  
 Address: Пловдив  
 Phone: 0877768013  
 Email: Kalin\_kulchew@abv.bg

VIN: YV1MK204282043695

Year: 2008

Make: Volvo

Model: C30

Odometer: 298984 km

Vehicle Software Version: V44.20

Diagnostic Application Version: 3.12.035

Test Time: 2019-06-04 09:49:32

Diagnostic path: Automatically Search > Health Report > DTC Report

### Inspection Result



#### Diagnostic Result

Fault	( 7 )	
ECM(Engine Control Module)	( 4 )	Abnormal
		ECM-0420 Three-way Catalytic Converter (TWC) Efficiency, Bank 1. Signal Too Low ECM-1632 Generator. Faulty Signal ECM-0620 Generator. Signal Too Low ECM-0303 Misfire Cylinder 3. Signal Too High
ABS(Anti-lock Braking System)	( 6 )	Abnormal
		ABS-0115 Communication Between Control Modules. Communication With The Steering Wheel Module (SWM). Signal Missing ABS-0101 Communication Between Control Modules. Communication Problems With The Engine Control Module(ECM) ABS-E000 Control Module Communication. Faulty Communication ABS-0109 Communication Between Control Modules. Steering Wheel Module (SWM), Internal Fault ABS-0058 Power Supply. Voltage Too High ABS-0118 Power Supply For The Body Sensor Cluster Stability Sensor (BSC). Voltage Too High
SRS(Supplemental Inflatable Restraint System)	( 3 )	Abnormal
		SRS-0002 SRS Indicator Lamp. Signal Missing

SRS-0005 Power Supply From The Battery. Voltage Too Low  
SRS-0006 Power Supply From The Battery. Voltage Too High

CEM(Central electrical  
module)

( 8 )

Abnormal

CEM-8F42 Relay, Tailgate Wiper Motor. Faulty Signal  
CEM-8F28 Relay, Rear Washer Motor. Internal Fault  
CEM-8F26 Relay, Front Windshield Washer Motor. Internal  
Fault  
CEM-DE49 Communication With The Steering Wheel Module  
(SWM). Signal Missing  
CEM-8A09 Low Beam Right. Faulty Signal  
CEM-6C44 Steering Column Lock Module (SCL). Faulty Signal  
CEM-E000 Communication With Control Module. Faulty  
Communication  
CEM-1C04 30-power Supply. Signal Too High

DIM(Driver information  
module)

( 1 )

Abnormal

DIM-0001 Mileage. Manipulated.

CCM(Climate control  
module)

( 2 )

Abnormal

CCM-0070 Configuration Fault. Faulty Identification  
CCM-DD34 Air Quality Sensor No Communication

SWM(Steering wheel  
module)

( 2 )

Abnormal

SWM-0A11 Communication With Control Modules. Signal  
Missing.  
SWM-0201 Steering Wheel Angle Sensor. Faulty Signal.

Normal

( 5 )

PDM(Passenger door  
module)

Normal

DDM(Driver door  
module)

Normal

AUD(Audio Module)

Normal

ICM(Infotainment  
Control Module)

Normal

IAM(Integrated Audio  
Module)

Normal