

## Vehicle diagnostic report



Shop Name: www.диагностика.бг  
 Address: Пловдив  
 Phone: 0877768013  
 Email: Kalin\_kulchew@abv.bg

VIN: KMHSH81WR8U272802

Year: 2008

Make: Hyundai

Model: Santafe(CM)

Odometer:

Vehicle Software Version: V50.70

Diagnostic Application Version: 3.12.036

Test Time: 2019-10-20 12:59:55

Diagnostic path: 16 PIN DLC > Select Menu Manually > General > Santafe(CM) > 2008 > D 2.2 TCI-D

## Inspection Result



## Diagnostic Result

Fault		( 5 )
ECM (Engine Control Module)(CPF-)	( 2 )	Abnormal
	P1661 Cruise Control Indicator Lamp-Malfunction	Present
	P0101 Mass or Volume Air Flow Circuit Range/Performance	Present
ECM (Engine Control Module)(CPF+)	( 2 )	Abnormal
	P1661 Cruise Control Indicator Lamp-Malfunction	Present
	P0101 Mass or Volume Air Flow Circuit Range/Performance	Present
TCM (Transmission Control Module)	( 1 )	Abnormal
	P0605 Internal Control Module Read Only Memory(Rom) Error	Present
Airbag(GEN)	( 1 )	Abnormal
	B1102 Battery Voltage Low	History
Airbag(NAS)	( 1 )	Abnormal
	B1102 Battery Voltage Low	History
Normal		( 6 )
ABS (Anti-lock Braking System)		Normal
AC (Air Conditioning)		Normal
BCM (Body Control Module)		Normal
4WD Control		Normal
IMM (Immobilizer)		Normal

