

Vehicle diagnostic report



Shop Name: www.диагностика.бг

Address: Пловдов

Phone: 0877768013

Email: Kalin_kulchew@abv.bg

VIN: WDD2211841A110825

Year:

Make: Mercedes

Model: 221.184 - S 450 4MAT

Odometer: 230397km

Vehicle Software Version: V49.11

Diagnostic Application Version: 3.12.035

Test Time: 2019-06-11 20:24:24

Diagnostic path: Automatically Search

Inspection Result



Diagnostic Result

Fault (10)

RevETR_LF - Left Front Reversible Emergency Tensioning Reactor(Chassis CAN Bus)	(1)	Abnormal
	5302 Internal Control Unit Reset By Program(Further Test: Press Button F3 Or F7.)	Stored
RevETR_RF - Right Front Reversible Emergency Tensioning Reactor(Chassis CAN Bus)	(1)	Abnormal
	5302 Internal Control Unit Reset By Program(Further Test: Press Button F3 Or F7.)	Stored
EIS - Electronic Ignition Switch(Interior CAN Bus)	(3)	Abnormal
	9006 Terminal 30B: NOT PRESENT / Undervoltage Supply	Stored
	9005 Terminal 30: Undervoltage / NOT PRESENT	Stored
	9001 Undervoltage Supply	Stored
SAM_DR - Driver Signal Acquisition And Actuation Module(Interior CAN Bus)	(1)	Abnormal
	90D0 Component Switch Illumination Or Line To Component Has Short Circuit Or Open Circuit.	Current and stored

BNS - Vehicle Power Supply Control Module(Chassis CAN Bus)	(5)	Abnormal
	9013 CAN Controller: CAN Bus OFF	Stored
	9014 The Consumer Shutoff Is Active.	Stored
	9016 Component G1/4(Starter Battery) Has Undervoltage.	Stored
	9018 Component G1(Vehicle Electrical System Battery) Has Undervoltage.	Stored
	9027 No CAN Message Received From Component Engine Control Module.	Stored
SCM - Steering Column Module(Chassis CAN Bus)	(1)	Abnormal
	9367 No CAN Message Was Received From Control Unit CDI.or No CAN Message Was Received From Control Unit ME-SFI.	Stored
DCM_FL - Door Control Module Front Left(Interior CAN Bus)	(1)	Abnormal
	900A The Mirror Heater Has Open Circuit.	Current and stored
DCM_FR - Door Control Module Front Right(Interior CAN Bus)	(1)	Abnormal
	900A The Mirror Heater Has Open Circuit.	Current and stored
DS_LF - Left Front Dynamic Seat(Interior CAN Bus)	(1)	Abnormal
	9200 The Module Carrier For The Backrest Is Defective.	Stored
DS_RF - Right Front Dynamic Seat(Interior CAN Bus)	(1)	Abnormal
	9200 The Module Carrier For The Backrest Is Defective.	Current and stored
Normal (29)		
TCM - Transmission Control Module(Drive Train CAN Bus)		Normal
ISM - Intelligent Servo Module(Drive Train CAN Bus)		Normal
ABR - Adaptive Brake(Chassis CAN Bus)		Normal
EPB - Electric Parking Brake(Front End CAN Bus)		Normal
Suspension(Chassis CAN Bus)		Normal
SRS - Supplemental Inflatable Restraint System(Chassis CAN Bus)		Normal
CGW - Central Gateway(Central CAN Bus)		Normal

XALWA_L - Xenon Headlamp, Left(Front End CAN Bus)	Normal
XALWA_R - Xenon Headlamp, Right(Front End CAN Bus)	Normal
OCP - Overhead Control Panel(Interior CAN Bus)	Normal
UCP - Upper Control Panel(Interior CAN Bus)	Normal
COU[ZBE] - Central Operating Unit(Telematic CAN Bus)	Normal
REAR SAM - Rear Signal Acquisition And Actuation Module(Interior CAN Bus)	Normal
System Diagnosis(Diagnosis CAN Bus)	Normal
IC - Instrument Cluster(Central CAN Bus)	Normal
ASSYST Active Service System(Diagnose CAN Bus)	Normal
ASSYST PLUS(Diagnose CAN Bus)	Normal
NSA - Night Vision Assist(Vehicle Dynamics CAN Bus)	Normal
PTS - PARKTRONIC(Interior CAN Bus)	Normal
COMAND - COMAND With Integral Telematics gateway(MOST Network Management, Diagnosis Gateway)	Normal
CTEL - Mobile Phone Adapter With Universal Interface	Normal
ZAN - Central Display	Normal
DCM_RL - Door Control Module Rear Left(Interior CAN Bus)	Normal
DCM_RR - Door Control Module Rear Right(Interior CAN Bus)	Normal
ESA_FL - Electric Seat Adjustment Front Left(Interior CAN Bus)	Normal
ESA_FR - Electric Seat Adjustment Front Right(Interior CAN Bus)	Normal
ESA_R - Electric Seat Adjustment Rear(Interior CAN Bus)	Normal

DSP - Pneumatic Pump
For Dynamic
Seat(Interior CAN Bus)

Normal

AC - Air
Conditioning(Interior
CAN Bus)

Normal