

## Vehicle diagnostic report



Shop Name: www.диагностика.бг  
 Address: Пловдов  
 Phone: 0877768013  
 Email: Kalin\_kulchew@abv.bg

VIN: WDD2120571A067133

Year:

Make: Mercedes

Model: 212.057 - E 350 CGI

Odometer: 176685km

Vehicle Software Version: V49.11

Diagnostic Application Version: 3.12.035

Test Time: 2019-06-16 14:25:14

Diagnostic path: Automatically Search

## Inspection Result



## Diagnostic Result

**Fault ( 8 )**

Fault	( 8 )	Abnormal
<b>ME - Motor Electronics</b>	<b>( 3 )</b>	<b>Abnormal</b>
0856 The Coolant Temperature Is Below The Coolant Thermostat Specified Temperature.		STORED
2035 Component "Y94 (Quantity Control Valve)" Has An Electrical Fault Or An Open Circuit.		STORED
2269 The Pressure In The Fuel Low Pressure Circuit Is Too High.		STORED
<b>PTS - PARKTRONIC(N62)</b>	<b>( 1 )</b>	<b>Abnormal</b>
d12b00 Communication With Front PARKTRONIC Warning Element 1 Has A Malfunction._		STORED
<b>SGR - Radar Sensors Control unit(N62/2)</b>	<b>( 5 )</b>	<b>Abnormal</b>
520400 Radar Sensor 2 Is Disrupted By Interference From An External Transmitter.		STORED
755200 CAN Message "Status Of Warning Lamp " Blind Spot Assist"" From Control Unit "N69/1 (Left Front Door Control Unit)" Is Faulty Or Not Available.		STORED
630700 CAN Communication With Component "B29/3 (Right Front Bumper DISTRONIC (DTR) Sensor)" Has A Malfunction.		STORED
620700 CAN Communication With Component "B29/2 (Left Front Bumper DISTRONIC (DTR) Sensor)" Has A Malfunction.		STORED
530400 Radar Sensor 3 Is Disrupted By Interference From An External Transmitter.		STORED

RevETR_LF - Left Front Reversible Emergency Tensioning retractor(A76)	( 1 )	Abnormal
	530a00	STORED
RevETR_RF - Right Front Reversible Emergency Tensioning retractor(A76/1)	( 1 )	Abnormal
	530a00 Multifunction Output 5 Has A Malfunction.	STORED
Rear SAM - Rear Signal Acquisition And Actuation module(N10/2)	( 2 )	Abnormal
	U113E00 Communication With The Battery Sensor Has A Malfunction._	STORED
	U100800 LIN Bus 1 Has A Malfunction._	STORED
SRS - Supplemental Restraint system(N2/10)	( 2 )	Abnormal
	d18d Communication With The Right Sensor For Function " Active Engine Hood" Has A Malfunction.	STORED
	d18c Communication With The Left Sensor For Function " Active Engine Hood" Has A Malfunction.	STORED
DCU_RF - Right Front door(N69/2)	( 6 )	Abnormal
	975515 The Output For The Exit Lamp Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	STORED
	9dfb13 The Output For Mirror Housing Adjustment Has A Malfunction.There Is An Open Circuit.	STORED
	a80c15 The Output For The Indicator Lamp " Blind Spot Assist" Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	STORED
	a80815 The Output For The Warning Lamp " Blind Spot Assist" Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	STORED
	9df701 The Mirror Glass Sensor For The Horizontal Position Has A Malfunction.There Is A General Electrical Fault.	STORED
	9df301 The Mirror Glass Sensor For The Vertical Position Has A Malfunction.There Is A General Electrical Fault.	STORED
<b>Normal</b>	<b>( 27 )</b>	
FSCU - Control Unit'Fuel pump'(N118)		Normal
ISM - Shift module(A80)		Normal
TCM - Transmission Control Module		Normal
ESP(R) - Electronic Stability program(N30/4)		Normal
DTR - DISTRONIC(A89)		Normal
MFK - Multifunction camera(A40/11)		Normal
OCP - Overhead Control panel(N70)		Normal
EZS - Electronic Ignition lock(N73)		Normal
SCCM - Steering Column module(N80)		Normal

Driver-side SAM - Front Signal Acquisition And Actuation module(N10/1)	Normal
XALWA_L - Left Xenon headlamp(E1n1)	Normal
XALWA_R - Right Xenon headlamp(E2n1)	Normal
CGW[ZGW] - Central gateway(CGW[ZGW])	Normal
COU[ZBE] - Audio/COMAND Operating Unit	Normal
ZAN - Audio/COMAND display(A40/8)	Normal
Audio/COMAND - Audio Or COMAND(A2-A2/56-A40/3)	Normal
ICI - InCar Internet	Normal
IC - Instrument cluster(A1)	Normal
SOUND - Sound system(N40/3)	Normal
CTEL - Telephone Japan	Normal
ESA'Front Passenger' - Electric Seat Adjustment 'Front passenger'(N32/2)	Normal
ESA 'Driver' - Electric Seat Adjustment 'Drive'(N32/1)	Normal
DCU_LF - Left Front door(N69/1)	Normal
DCU_LR - Left Rear door(N69/3)	Normal
DCU_RR - Right Rear door(N69/4)	Normal
AC - Air Conditioning(N22/7)	Normal
STH - Stationary heater(A6n1)	Normal