

Vehicle diagnostic report



Shop Name: www.диагностика.бг

Address: Пловдов

Phone: 0877768013

Email: Kalin_kulchew@abv.bg

VIN: WVVZZZ9NZ2D024093

Year: 2002

Make: VW

Model:

Odometer:

Vehicle Software Version: V28.50

Diagnostic Application Version: 3.12.035

Test Time: 2019-05-23 19:06:17

Diagnostic path: Health Report

Inspection Result



Diagnostic Result

Fault

(4)

01 Engine Control Module 1

(3)

Abnormal

P0116 Engine Coolant Temperature Sensor 1 : Circuit Range/Performance
 P0130 O2 Sensor Circ.,Bank1-Sensor1 : Malfunction
 P1570 Engine Control Module (ECM) Disabled

03 Brakes 1

(1)

Abnormal

01314 Engine Control Module (ECM)

Check DTC Memory

08 Air Conditioning

(7)

Abnormal

00818 Evaporator Vent Temperature Sensor

Open circuit/short circuit to B+

01271 Temperature Flap Motor

Open circuit/short circuit to B+

01271 Temperature Flap Motor

locked or has no voltage supply

01271 Temperature Flap Motor

Short circuit to ground

01271 Temperature Flap Motor

Short circuit to B+

01596 Fresh/recirc. Air Flap Position Motor

locked or has no voltage supply

01596 Fresh/recirc. Air Flap Position Motor

Short circuit
to ground

44 Steering Assistance (1)

Abnormal

00816 Power Steering Sensor

Short circuit
to ground

Normal

(7)

09 Central Electrics

Normal

15 Airbag

Normal

17 Dash Board

Normal

19 Gateway

Normal

25 Immobilizer

Normal

45 Interior Monitoring

Normal

46 Central Module
Comfort System

Normal