

Vehicle diagnostic report



Shop Name: WWW.ДИАГНОСТИКА.БГ

Address: диагностика Пловдив

Phone: 0877768013

Email: Kalin_kulchew@abv.bg

VIN: WAUZZZ4H3AN002621

Year: 2010

Make: Audi

Model:

Odometer: 372744 km

Vehicle Software Version: V28.55

Diagnostic Application Version: 3.12.036

Test Time: 2019-08-11 12:44:29

Diagnostic path: Health Report

Inspection Result



Diagnostic Result

Fault

(11)

Fault	(11)	
01 Engine Control Module 1	(2)	Abnormal
	P24A300 Particulate Filter Restriction - Soot Accumulation Bank 2	active/static
	P162400 Requirement - Malfunction Lamp On - Active	active/static
08 Air Conditioning	(2)	Abnormal
	B10D822 Right Side Window Defroster Door Motor - Upper Limit Exceeded	active/static
	B10D829 Right Side Window Defroster Door Motor - Implausible Signal	passive/abiogenesis
09 Central Electrics	(1)	Abnormal
	01771 Headlamp Range Control Module	Check DTC Memory
11 Engine Control Module 2	(1)	Abnormal
	P202100 Intake Manifold Runner Pos. Sen. /Switch Circuit Bank 2 - Low	active/static
13 Adaptive Cruise Control	(4)	Abnormal
	C110300 Adaptive Cruise Control Sensor - Misadjusted	active/static
	C110300 Adaptive Cruise Control Sensor - Misadjusted	active/static
	C110300 Adaptive Cruise Control Sensor - Misadjusted	active/static
	U111300 Function Limitation Due To Received Malfunction Value	passive/abiogenesis

34 Ride Control System	(2)	Abnormal
	C104807 Level Control System Sensor - Mechanical Malfunction	passive/abiogenesis
	C10C800 Function Deactivation Active	passive/abiogenesis
55 Headlight Regulation	(3)	Abnormal
	U111200 Function Limitation Due To Implausible Message	passive/abiogenesis
	C108413 Right Stationary AFS - Open Circuit	passive/abiogenesis
	C108000 Left-/right Hand Driving Switch-over Active	active/static
6C Camera System Rear View	(1)	Abnormal
	02203 Audio-/video Input 1	Open Circuit
84 Night Vision	(1)	Abnormal
	B11E129 Video Line For Night Vision System - Implausible Signal	active/static
85 On-Board Camera	(1)	Abnormal
	U111300 Function Limitation Due To Received Malfunction Value	passive/abiogenesis
8E Image Processing Electronics	(1)	Abnormal
	C110800 Function Limitation Due To Missing Image Information	passive/abiogenesis
Normal (31)		
02 Transmission Control Module		Normal
03 Brakes 1		Normal
05 Kessy		Normal
06 Seat Adjustment Passenger Side		Normal
10 Parking Assistance 2		Normal
15 Airbag		Normal
16 Steering Column Electronics		Normal
17 Dash Board		Normal
18 Auxiliary Parking Heater		Normal
19 Gateway		Normal
22 All Wheel Control		Normal
36 Seat Adjustment Driver Side		Normal
3B Sensor Electronics		Normal
3C Lane Change Assistant		Normal
42 Door Electronics Driver Side		Normal
46 Central Module Comfort System		Normal

47 Sound System	Normal
52 Door Electronics Passenger Side	Normal
53 Parking Brake	Normal
56 Radio	Normal
5F Information Control Unit 1	Normal
62 Door Electronics Rear Left	Normal
6D Deck Lid Control Unit	Normal
6F Central Module Comfort System 2	Normal
72 Door Electronics Rear Right	Normal
81 Gear Shift Control Module	Normal
88 Multi Contour Seat Driver Side	Normal
89 Multi Contour Seat Passenger Side	Normal
8B Adaptive Cruise Control 2	Normal
8F Pretensioner Front Left	Normal
90 Pretensioner Front Right	Normal