

Vehicle diagnostic report



Shop Name: WWW.ДИАГНОСТИКА.БГ
 Address: диагностика Пловдив
 Phone: 0877768013
 Email: Kalin_kulchew@abv.bg

VIN: WDD2042081F142601

Year:

Make: Mercedes

Model: 204.208 - C 220 CDI

Odometer: 245311km

Vehicle Software Version: V49.21

Diagnostic Application Version: 3.12.035

Test Time: 2019-07-28 12:45:25

Diagnostic path: Automatically Search

Inspection Result



Diagnostic Result

Fault	(7)	
ECM - Engine Control Module(CDI)	(2)	Abnormal
	2283 R9/1 (Cylinder 1 Glow Plug)	STORED
	2054 B50 (Fuel Temperature Sensor)	STORED
ESP - Electronic Stability program(N30/4)	(1)	Abnormal
	6264 One Or More Signals Sent From Control Unit "Combustion Engine" Via The CAN Bus Is Implausible.	STORED
PTS - PARKTRONIC(N62)	(2)	Abnormal
	925395 The Inner Right Front Distance Sensor Has A Malfunction.The Mechanical Setup Is Not OK.	CURRENT And STORED
	924e95 The Inner Left Front Distance Sensor Has A Malfunction.The Mechanical Setup Is Not OK.	CURRENT And STORED
Driver-side SAM - Front Signal Acquisition And Actuation Module	(2)	Abnormal
	B162A15 The Left Low Beam Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	STORED
	B162E15 The Right Low Beam Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	STORED
REAR SAM - Rear Signal Acquisition And Actuation Module	(5)	Abnormal
	B16E715 The Output For The Left License Plate Lamp Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	CURRENT And STORED

	B16EB15 The Output For The Right License Plate Lamp Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	CURRENT And STORED
	B16FF15 The Output For The Left Rear Fog Light Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	STORED
	B1A6313 The Glass Breakage Sensor Has A Malfunction.There Is An Open Circuit.	STORED
	B280115 The Left Inner Stop Lamp And Taillamp Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	STORED
SRS - Supplemental Restraint System	(2)	Abnormal
	B005013 The Belt Buckle " Driver" Has A Malfunction.There Is An Open Circuit.	STORED
	B005213 The Belt Buckle " Front Passenger" Has A Malfunction.There Is An Open Circuit.	STORED
CGW[ZGW] - Central Gateway	(2)	Abnormal
	U102700 Chassis CAN Bus OFF Fault_	STORED
	U102700 Chassis CAN Bus OFF Fault_	CURRENT And STORED

Normal (13)

ESM[EWM] - Electronic Selector module(N15/5)	Normal
TCM - Transmission Control Module	Normal
EZS - Electronic Ignition lock(N73)	Normal
SCM - Steering Column Module	Normal
COU[ZBE] - Audio/COMAND Operating Unit	Normal
ZAN - Audio/COMAND Display	Normal
Audio/COMAND - Audio Or COMAND(A2-A2/56-A40/3)	Normal
IC - Instrument cluster(A1)	Normal
DCU_LR - Left Rear door(N69/3)	Normal
DCU_RR - Right Rear door(N69/4)	Normal
DCU_LF - Left Front door(N69/1)	Normal
DCU_RF - Right Front door(N69/2)	Normal
AC - Air Conditioning(N22/7)	Normal