

## Vehicle diagnostic report



Shop Name: www.диагностика.бг  
 Address: Пловдив  
 Phone: 0877768013  
 Email: Kalin\_kulchew@abv.bg

VIN: WBAUG51020JU05079

Year: 2004.05

Make: BMW

Model: 120d

Odometer: 185274 km

Vehicle Software Version: V50.30

Diagnostic Application Version: 3.12.036

Test Time: 2019-11-08 10:13:49

Diagnostic path: Automatically Search > Health Report > Fault Report

### Inspection Result



### Diagnostic Result

#### Fault ( 10 )

<b>CAS (Car Access System - CAS/FEM/BDC)</b> ( 2 )		Abnormal
	A0B2 CAS: Supply, Terminal 30E/30L	History
	A0B5 CAS: Fault, Road Speed Signal	History
<b>ECM (Engine Control Module - DME/DDE)</b> ( 10 )		Abnormal
	3EFC DDE: Thermal Oil-Level Sensor	Current
	4203 DDE: Glow Control Unit	Current
	4A25 DDE: Intelligent Battery Sensor, Communication	History
	4A27 DDE: Intelligent Battery Sensor, Communication	Current
	4993 Message Error (Instrument Panel, 0x1B4), DDE Receiver, Instrument Panel Transmitter	History
	49A3 Message Error (Ambient Temperature, 0x310), DDE Receiver, Instrument Panel Transmitter	Current
	4BF8 Message Error (Range, 0x330), DDE Receiver, Instrument Panel Transmitter	Current
	4A56 DDE: Power Management, Battery	Current
	4A07 DDE: Alternator	History
	4A66 DDE: Power Management, Vehicle Electrical System	History
<b>TCM (Transmission Control Module - EGS/DKG/SMG)</b> ( 2 )		Abnormal
	CF23 No Message From The Instrument Panel, Receiver DKG/EGS, Transmitter AHM/KOMBI	History

	CF21 No Message From The KOMBI, Receiver DKG/EGS, Transmitter DSC/KOMBI	History
ABS (Anti-Lock Braking System - DSC)	( 2 )	Abnormal
	D358 Message (KOMBI, 0x784) Missing, Receiver DSC, Transmitter KOMBI	History
	D359 Message (KOMBI, 0x816) Missing, Receiver DSC, Transmitter KOMBI	History
SGM-ZGM (Safety And Gateway Module (ZGM) - JBE/JBE2/JBBF/KGM)	( 2 )	Abnormal
	A6CF JBE: AUC Sensor	Current
	A6D1 JBE: Auxiliary-Water Pump	Current
SINE (Siren And Tilt Sensor)	( 1 )	Abnormal
	9D12 SINE: Internal Battery	History
CD (Control Display - CIC/CCC-BO/CHAMP-BO/M-ASK-BO/RAD/RAD2-BO)	( 1 )	Abnormal
	ABD1 RAD2: No Connection To Aerial	History
PDC (Park Distance Control)	( 5 )	Abnormal
	9E3A PDC: Lines, Front Middle Right, Ultrasonic Sensor	History
	9E37 PDC: Lines, Front Left, Ultrasonic Sensor	History
	9E38 PDC: Lines, Front Right, Ultrasonic Sensor	History
	9E39 PDC: Lines, Front Middle Left, Ultrasonic Sensor	History
	9E3D PDC: Acoustic Generator, Front	Current
FRM (Footwell Module)	( 1 )	Abnormal
	9CC4 FRM: Mirror Heating, Passenger's Side, Faulty	History
AC (Air Conditioning - IHKA)	( 1 )	Abnormal
	9C7B IHKA: Interior-Temperature-Sensor Fan	History
<b>Normal</b>		<b>( 7 )</b>
EKPS (Electronic Fuel Pump)		Normal
SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)		Normal
DWA (Antitheft Alarm System)		Normal
FZD (Function Center, Roof)		Normal
IC (Instrument Cluster - INSTR)		Normal
CD-GW/M-ASK-GW (Control Display (Gateway) - CIC-GW/CCC-GW/CHAMP-GW/RAD2-GW)		Normal
RLSS (Rain/Light Sensor)		Normal